


SOLIDWORKS DRAWING

Linework is accurate and connected properly



FUSION 360 DRAWING

Virtually NONE of the linework is connected properly (take a close look at the top and the letters)

