





Here in these examples the Daylight lines (Finished ground) extends beyond the existing ground? Why? This results in correct cut/ fill volumes. Could it be my assembly or corridor surface boundary? Please explain!



Section at 1 point

Basic lane with Daylight multi-intercepts