Scan and model far out:

Scan when zoomed in to the South west corner disappears! Does this mean as I get closer the laser scan is represented by Revit more accurately?