
A
B
C
D
1
3
(-100)
JOIST
(-300)
(-100)
BEAM
(-85)
(0)
BEAM
(0)


THE SIDE OF THE BEAM SYSTEM, ALONG AXIS B, SHOULD BE +100 FOT THE BEAMS TO BE AT THE GOOD LEVEL
A
BEAM -100
BEAM SYSTEM ELEVATION : +100
BEAM -300
B
BEAM -85
C
BEAM SYSTEM ELEVATION : 0
TOP OF STEEL (-150)
TOP OF STEEL (-100)
TOP OF STEEL (-50)
AUTOMATIC TOP OF STEEL (-250) HAVE TO BE MANUALY CORRECTED TO -150
AUTOMATIC TOP OF STEEL (-200) HAVE TO BE MANUALY CORRECTED TO -100
BEAM -100
BEAM -0
AUTOMATIC TOP OF STEEL (-150) HAVE TO BE MANUALY CORRECTED TO -150
THIS SIDE OF THE BEAM SYSTEM IS OK AT 0
BEAM 0
D


A
B
C
D
BEAM SYSTEM ELEVATION ON THIS SIDE SHOULD BE + 100
BEAM SYSTEM ELEVATION : 0

SECTION