

Factory Home Insert Annotate Parametric Content View Manage Output Add-Ins Online Express Tools Vault

Power Multiple Dimension Dimension Multiline Text Leader Note Surface Texture Welding Balloons Part Reference Assembly Properties BOM Parts Hole Fits Table Viewport/Scale Area Title Scale Base Edit View

External References

File References

Reference ...	Status	Size
0507-00	Open...	101

Details

Reference ...

Status

Size

Type

Date

Saved Path

Found At

Latest Versi...

[-] [Tc] [2D Wireframe]

技术要求
1、锐棱倒钝

2	0507-02	zhiban2	1	45			
1	0507-01	zhiban	1	45			
Item	Code Number	Part Name	Qty	Material	Mass (M/M)	Note	
Part Name Region						zhijia	0507-00
Design	hp	2011/05/06	Selected	Phase Mark	Mass		
Verified					1:2		

Command:
Command: _QSAVE
Command:

0507-01.dwg

Factory Home Insert Annotate Parametric Content View Manage Output Add-Ins Online Express Tools Vault

Power Dimension Dimension Multiple Dimension Balloons Part Reference Assembly Properties BOM Parts List Hole List Fits Table Table Viewport/Scale Area Title Scale Base Edit View


Dimension Text Symbol Balloon BOM Table Layout Drawing views

External References

File References

Reference ...	Status	Size
0507-01	Open...	95.9

Details



Command:
Command: _QSAVE
Command:

Home

- Project Explorer (\$)
 - 0501
 - 050101
 - 0504
 - 0505
 - Drawing
 - Office
 - 通用件
- My Worklist
- My Shortcuts
- Add new group
- Home
- Project Explorer
- Item Master
- Change Order List

Drawing (C:\Users\hp\Documents\Vault\Drawing\)

Search Drawing

Name	State	Ver...	R...	Checked...	Crea...	Current O...
GS0506-005.dwg		1		2011/5/4 ...	Admin...	HP-PC\AUTO...
GS0506-004.dwg		1		2011/5/4 ...	Admin...	HP-PC\AUTO...
GS0506-000.dwg		1		2011/5/4 ...	Admin...	HP-PC\AUTO...
AutoCADBlockAttribu...	Work in Progress	1	A	2011/5/6 ...	Design	HP-PC\AUTO...
0507-01.dwg	Work in Progress	1	A	2011/5/6 ...	Design	HP-PC\AUTO...
0507-00.dwg	Work in Progress	1	A	2011/5/6 ...	Design	HP-PC\AUTO...
0506-00...		1		2011/5/4 ...	Admin...	HP-PC\AUTO...
0505-00...		1		2011/5/4 ...	Admin...	HP-PC\AUTO...
0505-00...		1		2011/5/4 ...	Admin...	HP-PC\AUTO...

History Uses Where

Latest Work in P

File Name	State	Created By	Checked In	Comment
0507-00.dwg	Work in Progress	Design	2011/5/6 15:08	

Open
View in Window...
Assign Item...
Go To Item
Check In...
Get / Checkout
Undo Check Out...
Change State...
Copy Design...
Create Shortcut
Delete
Purge...
Rename...
New Change Order
Add to Change Order
Go to Working Folder
Go To Folder


Properties

0507-00.dwg

System









Category Name	Engineering
Category Name (Historical)	Engineering
Change Order State	
Checked In	2011/5/6 15:08
Checked Out	
Checked Out By	
Checked Out Local Spec	
Checked Out Machine	
Classification	None
Comment	
Controlled By Change Order	False

Help Topics | Help Content | Properties

 **Preview Items** Find Duplicates View Results**Welcome to the Assign Item Wizard !**

Edit the item properties and select 'Next' to replace duplicate items.

Show:

Number	 Detail ID	Quantity	Primary File N...	Category Name	Title (Ite...	Descripti...	
  100017	-	-	0507-00.dwg	Assembly		0507-00	
  100019	2	1	0507-00.dwg	Part		zhiban2	
  100018	1	1	0507-00.dwg	Part		zhiban	

Total Items: 3 New Items Created: 3 Updated Items: 0

Click 'Next' to continue

< Back

Next >

Cancel

Help

Home

- Project Explorer (\$)
 - 0501
 - 050101
 - 0504
 - 0505
 - Drawing
 - Office
 - 通用件
- My Worklist
- My Shortcuts
- Add new group
- Home
- Project Explorer
- Item Master
- Change Order List

Drawing (C:\Users\hp\Documents\Vault\Drawing\)

Name	State	Ver...	R...	Checked...	Crea...	Current O...
GS0506-005.dwg		1		2011/5/4 ...	Admin...	HP-PC\AUTO...
GS0506-004.dwg		1		2011/5/4 ...	Admin...	HP-PC\AUTO...
GS0506-000.dwg		1		2011/5/4 ...	Admin...	HP-PC\AUTO...
AutoCADBlockAttribu...	Work in Progress	1	A	2011/5/6 ...	Design	HP-PC\AUTO...
0507-01.dwg	Work in Progress	1	A	2011/5/6 ...	Design	HP-PC\AUTO...
0507-...	Work in Progress	1	A	2011/5/6 ...	Design	HP-PC\AUTO...
0506-...		1		2011/5/4 ...	Admin...	HP-PC\AUTO...
0505-...		1		2011/5/4 ...	Admin...	HP-PC\AUTO...
0505-...		1		2011/5/4 ...	Admin...	HP-PC\AUTO...

History Uses Whe

Latest Work in

File Name	(Historical)	Created By	Checked In	Comment
0507-01.dwg	Work in Progress	Design	2011/5/6 15:08	


- Open
- View in Window...
- Assign Item...
- Go To Item
- Check In...
- Get / Checkout
- Undo Check Out...
- Change State...
- Copy Design...
- Create Shortcut
- Delete
- Purge...
- Rename...
- New Change Order
- Add to Change Order
- Go to Working Folder
- Go To Folder

Properties

0507-01.dwg

System

Category Name	Engineering
Category Name (Historical)	Engineering
Change Order State	
Checked In	2011/5/6 15:08
Checked Out	
Checked Out By	
Checked Out Local Spec	
Checked Out Machine	
Classification	None
Comment	
Controlled By Change Order	False







Help Topics Help Content Properties

Welcome to the Assign Item Wizard !

Edit the item properties and select 'Next' to replace duplicate items.

Show:

Number	 Detail ID	Quantity	Primary File N...	Category Name	Title (It...	Descripti...	
  100020	-	-	0507-01.dwg	Part		0507-01	

Total Items: 1 New Items Created: 1 Updated Items: 0

Click 'Next' to continue

< Back

Next >

Cancel

Help