





The Part 4040-15, have been quick changed several times, it's a derived part from an assembly.

I have already checked out all part ans update, but I get always the same problem.

