

Figure 1 – SCREEN SHOT - 3D VIEW IN REVIT




Figure 2 – SCREEN SHOT - PLAN VIEW IN REVIT (MECH DISCIPLINE)




Figure 3 - PRINTED TO PDF

Mechanical Settings

Setting	Value
Draw MEP Hidden Lines	<input type="checkbox"/>
Line Style	<Hidden>
Inside Gap	5/64"
Outside Gap	5/64"
Single Line	5/64"

VALVE SYMBOLS LOOK GOOD

NO MORE LINE BREAKS (BAD)

Figure 4 – SCREEN SHOT - "MEP HIDDEN LINES" TURNED OFF




Figure 5 - PRINTED TO PDF WITH "MEP HIDDEN LINES" OFF




Figure 6 - MEP HIDDEN LINES ON - COORDINATION DISCIPLINE