

Autodesk® Simulation Moldflow® Adviser
2014 Service Pack 2

Readme Notes

07-22-2013

Copyright notice

Autodesk® Simulation Moldflow® Adviser

© 2013 Autodesk, Inc. All rights reserved. Except as otherwise permitted by Autodesk, Inc., this publication, or parts thereof, may not be reproduced in any form, by any method, for any purpose.

Certain materials included in this publication are reprinted with the permission of the copyright holder.

Trademarks

The following are registered trademarks or trademarks of Autodesk, Inc., and/or its subsidiaries and/or affiliates in the USA and other countries: 123D, 3ds Max, Algor, Alias, Alias (swirl design/logo), AliasStudio, ATC, AUGI, AutoCAD, AutoCAD Learning Assistance, AutoCAD LT, AutoCAD Simulator, AutoCAD SQL Extension, AutoCAD SQL Interface, Autodesk, Autodesk Homestyler, Autodesk Intent, Autodesk Inventor, Autodesk MapGuide, Autodesk Streamline, AutoLISP, AutoSketch, AutoSnap, AutoTrack, Backburner, Backdraft, Beast, Beast (design/logo) Built with ObjectARX (design/logo), Burn, Buzzsaw, CAiCE, CFdesign, Civil 3D, Cleaner, Cleaner Central, ClearScale, Colour Warper, Combustion, Communication Specification, Constructware, Content Explorer, Creative Bridge, Dancing Baby (image), DesignCenter, Design Doctor, Designer's Toolkit, DesignKids, DesignProf, DesignServer, DesignStudio, Design Web Format, Discreet, DWF, DWG, DWG (design/logo), DWG Extreme, DWG TrueConvert, DWG TrueView, DWFx, DXF, Ecotect, Evolver, Exposure, Extending the Design Team, Face Robot, FBX, Fempro, Fire, Flame, Flare, Flint, FMDesktop, Freewheel, GDX Driver, Green Building Studio, Heads-up Design, Heidi, Homestyler, HumanIK, IDEA Server, i-drop, Illuminate Labs AB (design/logo), ImageModeler, iMOUT, Incinerator, Inferno, Instructables, Instructables (stylized robot design/logo), Inventor, Inventor LT, Kynapse, Kynogon, LandXplorer, LiquidLight, LiquidLight (design/logo), Lustre, MatchMover, Maya, Mechanical Desktop, Moldflow, Moldflow Plastics Advisers, Moldflow Plastics Insight, Moldflow Plastics Xpert, Moondust, MotionBuilder, Movimento, MPA, MPA (design/logo), MPI, MPI (design/logo), MPX, MPX (design/logo), Mudbox, Multi-Master Editing, Navisworks, ObjectARX, ObjectDBX, Opticore, Pipeplus, Pixlr, Pixlr-o-matic, PolarSnap, PortfolioWall, Powered with Autodesk Technology, Productstream, ProMaterials, RasterDWG, RealDWG, Real-time Roto, Recognize, Render Queue, Retimer, Reveal, Revit, RiverCAD, Robot, Scaleform, Scaleform Gfx, Showcase, Show Me, ShowMotion, SketchBook, Smoke, Softimage, SoftimageXSI (design/logo), Sparks, SteeringWheels, Stitcher, Stone, StormNET, Tinkerbox, ToolClip, Topobase, Toxik, TrustedDWG, T-Splines, U-Vis, ViewCube, Visual, Visual LISP, Voice Reality, Volo, Vtour, WaterNetworks, Wire, Wiretap, WiretapCentral, XSI.

All other brand names, product names or trademarks belong to their respective holders.

Contents

Chapter 1	Notice to our customers	1
Chapter 2	Summary of issues that have been addressed in Service Pack 2	3
Chapter 3	Known issues	5

Notice to our customers

1

In a continuing effort to provide high quality products, Autodesk has released Autodesk Simulation Moldflow Adviser 2014 Service Pack 2 (SP2), which fixes or addresses a variety of issues pertaining to the 2014 release. This README file highlights what has been fixed.

Requirement

Autodesk Simulation Moldflow Adviser 2014 must be installed before you can apply SP2. SP2 can then be installed directly, regardless of whether Service Pack 1 has been installed, since SP2 includes all fixes from SP1. If you have a language pack installed, select the relevant language from the Options dialog before installing SP2. If you do not select the language prior to installing SP2, the user interface will appear in English. To change the user interface language, select the relevant language from the Options dialog.

Summary of issues that have been addressed in Service Pack 2

2

- 1 Dual stack IPv6/IPv4 networks are supported for 64-bit Windows systems and also Linux 6 systems running at least version 6.1.
- 2 When using Vault to store files, models can be imported, the analysis sequence can be changed or cancelled, and the changes will be saved, as expected.
- 3 All surfaces are now included, when importing IGES files on non-English operating systems that use a comma as the decimal separator.
- 4 The Report Wizard works as intended when generating an html format report.
- 5 On Windows 8 operating systems, the additional right-mouse-button menu items that relate to modeling, and which are not available on other operating systems, have been removed.
- 6 For Education Suite customers only, some customers with machines that do not have serial number information in their machine BIOS might have experienced intermittent crashes. Machines that do not have serial number information in their machine BIOS now run as expected.

Known issues

3

If you are using an AMD GPU card, and depending upon the computer security settings, it is possible that your 3D analysis might fail.

To prevent this you will need to acquire full access to the

`C:\Windows\temp`

directory to which the GPUs need full access. To get full control of this directory, click on the

`C:\Windows\temp`

directory in Windows Explorer, and follow the prompt.