



this needs to be deleted from your assembly. this cannot co-exist with the side swale you have defined. if you want this slope to be what effects your corridor then you will have to delete the swale you have defined. this is true for both sides.