



.ipn file - source for the drawing with problems (top right).

If the source file is .iam, the drawing is normal.

.idw file, with problems - shows surfaces that are used to trim, but their visibility is turned off (as shown below).

The trouble is occurring with only one part. There are other parts in the assembly with trims, but they are shown normally.

If the source is an .iam, the drawing is normal.

