

THREAD : THREAD1

**Passes**

Tolerance: 0.0004 in

Threading Hand: Right hand...

Thread Depth: 0.04 in

Number of Stepdowns: 8

Thread Pitch: 0.0787402 in

Do Multiple Threads:

Infeed Mode: Constant i...

Infeed Angle: 0 deg

Fade Thread End:

Spring Pass:

Use cycle:

OK Cancel

