





This folder does Not Exist! Why is the Auto loader try to find these Items that are in the SAME :.\Designs\Workspace\... Path as the parts above????

This Sub-assembly has already been Successfully Vaulted!

- Parent Assembly 3-00298-013-01 was open prior to the Pack&Go to verify.
- Pack&Go fails on our New 64 bit Workstation with Two Disk Drives.
- Design Folder is on Second Drive (no Design Data is intentionally written to C: drive.)