

No material
Incorrect panel calculation model
The load has not been distributed correctly | there are no objects th
Number of errors:2
Number of warnings:1

- Display
- Errors
 - Warnings
 - Notes

Verify Close

Highlighting a line with an error message or warning selects objects connected with it.

