

## WHEN I OPEN THE PROJECT FOLDER

Name	Date modified	Type	Size
ReportTemplates	11.5.2011 18:46	File folder	
Related Files	10.8.2011 10:35	File folder	
Plant 3D Models	22.9.2011 11:56	File folder	
PID.DWG	22.8.2011 20:10	File folder	
Orthos	28.9.2011 14:39	File folder	
Isogen	6.7.2011 15:37	File folder	
ImportExportSettings	29.9.2010 16:09	File folder	
Equipment Templates	6.7.2011 15:37	File folder	
Drawing Templates	6.7.2011 15:37	File folder	
SubstitutionPalettes.xml	24.9.2010 16:28	XML Document	104 KB
Project.xml	22.9.2010 13:37	XML Document	2 KB
Project Iso Settings.xml	15.6.2011 18:18	XML Document	1 KB
PIDTo3dClassMapping.xml	15.6.2011 18:18	XML Document	922 KB
Metric_PipingPart.xml	20.7.2011 8:48	XML Document	19 KB
Metric_OrthoPart.xml	15.6.2011 18:17	XML Document	9 KB
IsoPart.xml	27.7.2011 16:18	XML Document	72 KB
ISO_ProjPart.xml	15.6.2011 18:17	XML Document	131 KB
DefaultConnectorsConfig.xml	31.3.2011 16:13	XML Document	21 KB
plot.log	9.3.2011 1:54	Text Document	5 KB
Drawing2.pnpperrors	27.9.2010 16:26	PNPERRORS File	1 KB
002.pcf	22.9.2010 18:33	PCF File	7 KB
Project.xml.lock	22.9.2010 13:41	LOCK File	0 KB
ProcessPower.dcfx	21.3.2011 15:48	DCFX File	156 KB
Piping.dcfx	27.3.2011 22:05	DCFX File	56 KB
Ortho.dcfx	13.6.2010 11:49	DCFX File	11 KB
ProcessPower.dcf	15.6.2011 18:21	DCF File	1 478 KB
Piping.dcf	22.9.2011 11:56	DCF File	39 974 KB
Ortho.dcf	22.9.2011 11:56	DCF File	166 400 KB
Iso.dcf	27.7.2011 19:21	DCF File	172 KB
projSymbolStyle.bak	25.3.2011 13:31	BAK File	426 KB
projSymbolStyle.dwg	24.5.2011 10:37	AutoCAD Drawing	420 KB

## WHEN I OPEN THE ISOGEN FOLDER

Name	Date modified	Type	Size
Final	9.8.2011 9:33	File folder	
Check	6.7.2011 15:37	File folder	
Inputs	26.7.2011 14:36	File folder	
Stress	29.6.2011 19:10	File folder	
Temp	11.5.2011 18:46	File folder	
Final.lck	22.9.2010 18:33	LCK File	0 KB
Check.lck	7.10.2010 11:54	LCK File	0 KB
isogenSymbols.dwg	13.6.2010 11:39	AutoCAD Drawing	75 KB
Stress.lck	7.10.2010 11:45	LCK File	0 KB

WHEN I OPEN THE FINAL ISOGEN FOLDER

Name	Date modified	Type	Size
Drawings	27.7.2011 18:10	File folder	
Messages	27.7.2011 16:18	File folder	
NEW	24.5.2011 13:18	File folder	
Quick	22.5.2011 15:11	File folder	
Final.alt	13.6.2010 11:39	ALT File	1 KB
Final.atr	24.5.2011 10:42	ATR File	1 KB
Final-ILF.dwg	10.6.2011 14:02	AutoCAD Drawing	198 KB
Final.bak	6.1.2011 14:43	BAK File	113 KB
Final-ILF.bak	7.6.2011 17:02	BAK File	196 KB
Final.ddf	10.6.2011 14:02	DDF File	4 KB
Final.fif	13.6.2010 11:39	FIF File	293 KB
Isogen.flx	6.1.2011 14:44	FLX File	1 KB
Final.mdl	24.5.2011 13:18	MLD File	1 KB
Final.opl	27.7.2011 16:18	OPL File	5 KB
Copy of Final.pos	7.3.2011 16:46	POS File	3 KB
Final.pos	25.3.2011 10:45	POS File	3 KB
plot.log	9.3.2011 20:58	Text Document	1 KB
PipelinesSettings.xml	22.9.2010 18:33	XML Document	1 KB

WHEN I OPEN THE CHECK ISOGEN FOLDER

Name	Date modified	Type	Size
Drawings	6.7.2011 15:37	File folder	
Messages	6.7.2011 15:37	File folder	
Quick	6.7.2011 15:37	File folder	
Check.alt	13.6.2010 11:39	ALT File	1 KB
Check.atr	27.3.2011 21:31	ATR File	1 KB
Check.bak	21.34	BAK File	50 KB
Check.ddf	9:36	DDF File	3 KB
Check.dwg	28.3.2011 21:06	AutoCAD Drawing	53 KB
Check.fif	13.6.2010 11:39	FIF File	293 KB
Check.mdl	27.3.2011 21:31	MLD File	1 KB
Check.opl	1.6.2011 9:02	OPL File	5 KB
Check.pos	13.6.2010 11:39	POS File	2 KB
Isogen.flx	15.6.2011 18:18	FLX File	1 KB
PipelinesSettings.xml	7.10.2010 11:54	XML Document	1 KB

## WHEN I OPEN THE STRESS ISOGEN FOLDER

Name	Date modified	Type	Size
↳ Drawings	29.6.2011 19:14	File folder	
↳ Messages	29.6.2011 19:10	File folder	
↳ Quick	11.5.2011 18:46	File folder	
Isogen.fls	22.9.2010 13:37	FLS File	1 KB
PipelinesSettings.xml	7.10.2010 11:45	XML Document	1 KB
Stress.alt	13.6.2010 11:39	ALT File	1 KB
Stress.atr	13.6.2010 11:39	ATR File	1 KB
Stress.ddf	28.2.2011 17:46	DDF File	2 KB
Stress.dwg	13.6.2010 11:39	AutoCAD Drawing	103 KB
Stress.fif	13.6.2010 11:39	FIF File	293 KB
Stress.mld	13.6.2010 11:39	MLD File	1 KB
Stress.opl	29.6.2011 19:10	OPL File	5 KB
Stress.pos	14.3.2011 9:26	POS File	2 KB