Problem with StubEnd in Isometrics

Pipe 1:


Steel Pipe, 10HC01, Butt Weld, Flange with Stub End

Pipe 2:


Plastic Pipe, Polypropylene, Fusion weld, Flange with Stub End

Pine 3:


Plastic Pipe, Polyvinylchloride, Glued, Flange with Stub End




StubEnd Pipe 1




StubEnd Pipe 2



StubEnd Pipe 3




Connections




Isometrics

Pipe 1 second Stub end is in the wrong way



Pipe 2

same problem



Pipe 3

i have 3 isometrics for 1 pipe with a flange...

