




ALL PART NO. RECTANGLE OR SQUARE ARE TIED
HOW CAN I EXPANDING.
EXAMPLE ([E8 B9 G10] [E8 B9 G10])

CONT'D ON
DWG#
SBR TANKS AIR
LINE-1-2
E 230234123
N 433846697
EL -1300

HOW CAN I SHOW THE COORDINATE AND ELEVATION
BY METER NOT TELEMETER
(THE DRAWING MODELED BY TELEMETER)

THE EXISTING PART SHOW WELD NO.
IN THE TABLE WELD LIST SUPPOSE NOT SHOWN IN THE
DRAWING OR THE TABLE BECAUSE THIS AN EXISTING
(ITEM NO. 12 & 13 IN THE TABLE WELD LIST)



OPEN END
E 230252496
N 433834081
EL -2281

[E8 B9 G10]
25 NS
OPERATOR WEST

[E8 B9 G10]
400X300 NS

[E8 B9 G10]
300 NS