

Terminal Strip Selection

Installation	Location	Terminal Strip	Quantity
	RCP4	TB43	14
	RCP1	TB13	2
	MCP	TB04	27
	RCP1	TB14A	13
	MACHINE	TB54	3
			2

New Edit

Done Help

The screenshot shows the software interface with the **Reports** ribbon selected. The ribbon contains the following items:

- Reports** (circled icon)
- Missing Catalog Data
- Electrical Audit
- DWG Audit
- Signal Error/List
- Reports
- Automatic Reports
- Report Format Setup
- User Attributes

Below the ribbon, the main workspace displays a 2D wireframe schematic titled **[-] [Top] [2D Wireframe]**. The schematic shows a power distribution system with the following components and connections:

- Power Source:** RA/SOS (8 Point) with 24VDC output.
- Terminal Blocks:** TBM3 (PCB-3) and TBM4 (PCB-4).
- Relays:** QX9.0 (1.1) and QX9.1 (2.1).
- Lighting:** LIGHT TOWER AL11 (BLU 902) and GRN.
- Wiring:** Solid lines represent power connections, and dashed lines represent signal or control connections.

Schematic Reports [X]

Report Name

- Bill of Material
- Missing Bill of Material
- Component
- From/To
- Component Wire List
- Connector Plug
- PLC I/O Address and Descriptions
- PLC I/O Component Connection
- PLC Modules Used So Far
- Terminal Numbers**
- Terminal Plan
- Connector Summary
- Connector Detail
- Cable Summary
- Cable From/To
- Wire Label

Terminal Numbers

Project

Active drawing

Category:

Freshen Project Database

Installation Codes to extract:

All

Blank

Named Installation

Installation:

List:

Location Codes to extract:

All

Blank

Named Location

Location:

List:

Report Generator [X]

Project Terminal numbers list for all locations (2 records)

WIRENO

918
919

Header

Time/Date	<input type="checkbox"/> Add	<input type="checkbox"/> First section only
Title Line	<input type="checkbox"/> Add	<input type="checkbox"/> First section only
Project Lines	<input type="checkbox"/> Add	<input type="checkbox"/> First section only
Column Labels	<input type="checkbox"/> Add	<input type="checkbox"/> First section only

Breaks

<input type="checkbox"/> Add page breaks
<input type="checkbox"/> Special breaks
Installation/Location/Terminal Strip ID
<input type="checkbox"/> Add special break values to header

Squeeze 1 2 3

Add blanks between entries

Sort User Post

Change Report Format

Edit Mode Put on Drawing Save to File Print Close Help Wide>

Terminal Numbers Data Fields to Report [X]

Available fields

- STRIP-ID
- TERM
- INST
- LOC
- SH
- SHDWGNAM
- BLKNAME
- MFG
- CAT
- ASSYCODE
- DESC1
- DESC2
- DESC3
- RATING1
- RATING2
- RATING3
- RATING4
- RATING5
- RATING6
- RATING7
- RATING8

<<Remove

<<Remove All

Fields to report

- WIRENO
- REF

Move Up

Move Down

Change field name/justification

Top Right

REF

OK+Save As

OK

Cancel

Help

Report Generator [X]

Project Terminal numbers list for all locations (2 records)

WIRENO	REF
918	32341
919	32342

Header

Time/Date	<input type="checkbox"/> Add	<input type="checkbox"/> First section only
Title Line	<input type="checkbox"/> Add	<input type="checkbox"/> First section only
Project Lines	<input type="checkbox"/> Add	<input type="checkbox"/> First section only
Column Labels	<input type="checkbox"/> Add	<input type="checkbox"/> First section only

Breaks

<input type="checkbox"/> Add page breaks
<input type="checkbox"/> Special breaks
Installation/Location/Terminal Strip ID
<input type="checkbox"/> Add special break values to header

Squeeze 1 2 3

Add blanks between entries

Sort User Post

Change Report Format

Edit Mode Put on Drawing Save to File Print Close Help Wide>

