



CONDUIT ELBOW ROTATED 45° DOWN
RISE-DROP DISPLAYED INCORRECTLY



CONDUIT ELBOW ROTATED 45° UP
RISE-DROP DISPLAYED PROPERLY



CONDUIT ELBOW ROTATED 45° DOWN
SHOULD LOOK LIKE THIS!

SINGLE-LINE DISPLAY
NEW DRAWING WITH 2014 'MEP' TEMPLATE