


Current Work Flow

SubAssembly: RETAINING WALL - DAYLIGHT




Issues:

- Edits to duplicated Flowcharts must be repeated over and over
- Each time Flowchart is copied user must edit Point and Link #'s to maintain consistency
- More difficult to troubleshoot

Desired Work Flow

SubAssembly: RETAINING WALL - DAYLIGHT



Benefits:

- Edits to Flowchart is only done once
- Point and Link #'s maintain consistency
- Simplified coding is easier troubleshoot