

2D CONTOUR: NECK SHAPE



Passes

Tolerance 0.01 mm

Sideways Compens...

Compensation Type In cut

Minimum Cutting Rad... 2 mm

Finishing Smoothing... 2 mm

Multiple Finishing Pas...

Finish Feedrate 1000

Repeat Finishing Pass...

Finishing Overlap 2 mm

Lead End Distance 2 mm

Outer Corner Mode

Tangential Fragment... 2 mm

Preserve Order

Both Ways

Roughing Passes

Multiple Depths

Stock to Leave

Smoothing


- Side Slots
- Long Slots 1
- Long Slots 2
- Neck Blank Rough
- Neck Shape Rough
- Neck Shape Com...
- Neck Blank Corne...
- Neck Blank Contour
- Neck ShapeCo...
- Form fil (2 Flat Sc...



54.694 mm

2

1



Test Object

Jig

Neck Blank Hold

Neck Outlined Ho

