

Line SW.23.31

Line SW.23.31

Line SW.23.72

Line SW.23.32

This drawing is posing a strange problem. The objects that are enclosed in the red revision cloud are blocks. We call them Catch Basins. We save this drawing as a \*.dxf file. We load this drawing to the Survey controller of Trimble. We also have a list of Co-ordinates for the corners of this object. On the site when we approach this area, these blocks appear displaced by about 50 Cm from their correct position. All other objects, blocks and lines are in their correct position. I purged the drawing, saved as a Wblock and tried out on site. The problem is defying solution. Can any one tell me why this is happening? and what is the solution. Thanks in advance.

