

Parcel Map Check Report

Client:

Client
Client Company
Address 1

Date: 2/10/2017 10:06:27 AM

Prepared by:

Preparer
Your Company Name
123 Main Street

Parcel Name: Survey Site - 1

Description:

Process segment order counterclockwise: False

Enable mapcheck across chord: False

North: 1,876,606.0026'

East: 6,329,225.7277'

Segment# 1: Line

Course: S 0° 00' 00" E

Length: 10.40'

North: 1,876,595.6026'

East: 6,329,225.7277'

Segment# 2: Line

Course: N 90° 00' 00" W

Length: 92.16'

North: 1,876,595.6026'

East: 6,329,133.5677'

Segment# 3: Line

Course: N 0° 00' 00" E

Length: 9.30'

North: 1,876,604.9026'

East: 6,329,133.5677'

Segment# 4: Line

Course: N 89° 19' 03" E

Length: 53.42'

North: 1,876,605.5390'

East: 6,329,186.9839'

Segment# 5: Line

Course: N 89° 19' 11" E

Length: 38.75'

North: 1,876,605.9990'

East: 6,329,225.7312'

Perimeter: 204.03'

Area: 907.78Sq.Ft.

Error Closure: 0.0050

Course: S 43° 55' 40" E

Error North : -0.00361

East: 0.00348

Precision 1: 40,806.00